TECHNICAL NOTE EDITION ANGLAISE



AUGUST 2001 77 11 306 702



		Туре	S/Section
Twingo	X06	8CD6JK	12 17
Kangoo	XC0	15BFLMP	12 17
	XC0	STW3	12 17
Clio	XB0	35BFHL	12 17
	XB0	PTW	12 17
	XB1	013457	12 17
	XB1	8DGK	12 17
	XB1	LNSTV	12 17
	XB2	В	12 17
Mégane	XA0	34BCDPW	12 17
	XA1	01234AD	12 17
	XA1	GHJLMRS	12 17
Laguna	XG0	16ABCDJ	12 17
	XG0	KLMNSUVY	12 17
Espace	XE0	02LNTUV	12 17

12 MOTORIZED THROTTLE BODY

Other sub-sections concerned:

17

Engine: XXX EURO 2000 and IF 2005

Gearbox: xxx

We inform you that none of the motorized throttle can be repaired.

After removal of the motorized throttle body, it is absolutely forbidden to:

- modify the position of the stop screws,
- open the throttle body.

The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of Renault.

[&]quot;The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.