

77 11 295 102 JANUARY 2000 **3393A**Service 0422

Laguna Safrane Espace

Type

X56 V

B54 N

JE0 6

S/Section

11

11

11

11


DEVELOPMENT OF THE CAMSHAFT PULLEY SCREW TIGHTENING DIRECTION

• Engine: L7X

• Gearbox: XXX Basic manual:

New camshaft pulley screws tightening direction.

These screws have one pitch on the left, the arrows (A) on the heads of these screws indicate the tightening direction.



[&]quot;The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.